


Environmental Working Group

Monthly Report

July 2014

ENVIRONMENTAL WORKING GROUP Relationship Organizational Chart



- Weekly Environmental Working Group (EWG) and EWG/Kiewit Alarie, a Partnership (KAP) meetings.
 - The EWG review its Action Items that include priority permit reviews, and deliverables to the Mattagami Extensions Coordinating Committee (MECC).
 - ▶ KAP gives EWG a construction up date every week and discusses any upcoming issues and/or urgent permit reviews.
 - Specific items that were discussed are below.
- The EWG members finalised their audit findings from June 30 to submit to Hatch for the final audit report.
- The EWG members coordinated the presentations for the MECC regarding Adam Creek (Hydronet, and Dan Gibson).
- On July 28-29, MCFN members of the EWG conducted a follow-up site visit with their Elders Advisory Group regarding the LMRP Rehabilitation Plan.
- On July 30, members of the EWG with Traditional Ecological Knowledge experts held a teleconference to discuss the Cultural Text (EA T&C 2c), the discussion was mainly related to focus on strategies to move the book forward.
- TTN members of the EWG continued to work on developing their own Elders Advisory Group as well as the Custodial Body.
- TTN members of the EWG worked on incorporating TEK into the SENES Erosion and Aquatic Reports for Adam Creek (commissioned by the MECC).
- Inclusion of a First Nation perspective on the Cost Benefit Analysis of Mitigating and Reducing Spill in Adam Creek. TTN and MCFN have completed their interviews and continue to look at ways to incorporate the First Nation perspective within the report. MCFN and TTN are now working independently to develop their own community's perspectives for the report. MCFN have completed their draft, TTN continues to conduct additional Elder interviews.
- MCFN and TTN of the EWG members continue to work on the development of a TEK Monitoring Program. The TEK Monitoring Program is intended to work with the OPG Environmental Effects Monitoring Plan to address term and condition 13 Aboriginal Knowledge.
- In an effort to improve the understanding of TEK, members of the EWG watched the documentary entitled "Watermark".

ACTIONS TO BE COMPLETED in 2014

		Jan	Feb	Mar	Apr	May	June	July	Aug	Sept	Oct	Nov	Dec
EWG Environnemental Due Diligence Audit	: #4												
WG Face to Face Meetings													
EWG present to the MECC the result of its	EWG present to the MECC the result of its review of the draft "Cost Benefit Analysis of												
Mitigating and Reducing Adam Creek Spill"	(Condition 4(c) and (e) of EA T&Cs) by Hatch.												
EWG present to the MECC the results and recommendations of periodic re-evaluations (Condition 10 of EA T&Cs).													
EA T&C 3a: Visual and Aesthetic Impacts	EWG present to the MECC "Environmental Effects												
EA T&C 4b: Hydrology, Fish and Aquatic Habitat	Monitoring Plan, Lower Mattagami Development"												
EA T&C 5b: Terrestrial Ecology	EWG present to the MECC "TEK - Environmental												
EA T&C 6: Erosion and Sedimentology	Effects Monitoring Plan, Lower Mattagami												
EA T&C 7: Mercury	Development"												
EA T&C 14: Permit Review and													
Compliance Monitoring Protocol													<u> </u>
EA T&C 3a: Visual and Aesthetic Impacts	EWG present to the MECC the results and												
	recommendations of Little Long Rehabilitation Plan												
EA T&C 5d: Terrestrial Ecology	EWG present to the MECC the results and												
	recommendations of Harmon Rehabilitation Plan												
	EWG present to the MECC the results and												
	recommendations of Kipling Rehabilitation Plan EWG present to the MECC the results and												'
	recommendations of Smoky Falls Rehabilitation												
	Plan												
EWG presents to the MECC a draft of the 'F	Peoples of the Moose River Basin', the cultural text												
outlined in EA T&C 2c.													
EWG read TEK book 'The Inconvenient Indian, A Curious Account of Native People in North													
America'.													
EWG watch TEK related films or documentaries (The Reel Injun, Cree Hunters of the Mistassini													
and Watermark).													
Completed: Pending: *Additional work still required to fulfill EA Term and Condition													

Construction General

• There were approximately 600 people in the camp this month. KAP continues to reduce the staff and craft numbers, reflecting the continued wind-down in construction activities.

Little Long

- KAP continued to work on closing out punch list items.
- Remedial polyurethane grout injections started on the powerhouse east wall construction joint. The work was nearing completion at month-end.
- Little Long Unit was 3 (Figure 1) was declared in service on January 19, 2014.



Figure 1: Little Long Unit 3

Harmon (Figure 2)

- Concrete injections continued, in an effort to eliminate leaks inside the powerhouse.
- AFI / Andritz installed and welded reinforcements for the intake hoist frame. KAP, OPG and Hatch representatives witnessed a deflection test post repairs. There was no significant deflection.
- The installation of the components for the heat trace for the generator surface cooling water outlet pipelines continues. The junction box, control panel, and thermostat were installed and electricians are glanding and terminating cables between them.
- KAP worked on correcting punch list items throughout the month.
- Harmon was declared in-service on June 3rd, 2014, three months ahead of the target in-service date.

Environmental Working Group July 2014 Report

Lower Mattagami River Project



Figure 2: Harmon overview

Kipling (Figure 3)

- Pipefitters installed pipes on various systems in and around the generator enclosure.
- The wicket gate links were all installed.
- Upper bracket assembly was completed in the Service Bay. The upper bracket was installed in the Unit.
- Generator cover plate installation has started at the centre of the generator enclosure.
- Electricians pulled and terminated cables for various systems throughout the powerhouse.
- On the night of July 30 / 31, the intake gate free fell on the dogging system. The gate and upper gate guides sustained damage. KAP stabilized the gate and has mobilized a team to investigate the incident and develop a recovery plan. It is forecasted that Kipling Unit 3 will be declared in service in December 2014.



Figure 3: Kipling Overview

Smoky Falls

- Excavation of the upstream cofferdam was completed. Material placement for the marine pad is complete (Figure 1).
- Wet excavation of the tailrace plug material was completed (Figure 2).
- Alstom continued to prepare Turbine/Generator components in the West Service Bay (WSB) and work inside the Units. They have completed the following tasks:
 - At Unit 1, Alstom completed construction of the Unit and turned it over to the commissioning team for wet testing.
 - At Unit 2, the overspeed detection system was installed, piping installation on various systems continues, generator covers were being prepared for installation, survey monuments were installed in the turbine pit, and the thrust bearing was filled with oil.
 - At Unit 3, rotor pole installation was completed. The generator shaft, wicket gate control mechanisms (links & levers) the rotor, the upper bracket, the upper generator shaft, and the upper guide bearing were all installed in the Unit.
- Unit 1 wet testing started on July 18th with the first rotation. Wet testing is ongoing and expected to be completed mid-to-late August.
- Unit 2 wet testing is forecast to start mid-August.
- Canmec completed repairs to the intake gate lintel sealing surface in water passages 1 and 2 (Unit 1). Load tests were completed for gates 1 and 2. Upon completion, the bulkhead gates were moved to water passages 3 and 4 (Unit 2).
- Canmec completed repairs to the intake gate lintel sealing surface in water passages 3 and 4 (Unit 2). Load tests were also completed for gates 3 and 4. Upon completion, the bulkhead gates were moved to water passages 5 and 6 (Unit 3).
- BOP Mechanical and Electrical installation work throughout the powerhouse continued to progress.
- It is forecasted that the in service date for Unit 1 will be in September 2014, November 2014 for Unit 2 and February 2015 for Unit 3.



Figure 4: Smoky Falls spur dike and marine pad/replacement beach



Figure 5: Smoky Falls tailrace

SPILLS									
No. c	No. of Spills: 3; Spill Reports 446-448 (see Figure 6 for LMRP spills breakdown).								
Classification of KAP Project Class			Project Cla	sification					
Spills: Minor – 2 Mode			r – 2 Mode	erate – 1 Major – 0 To Water - 0					
MOE Classificati				ion					
Non-reportable			reportable	- 2					
Reportable to M			rtable to N	IOE					
			-	Class C – 1					
			-	Class B – 0					
			-	Class A – 0					
Repo	rtable Spill	5							
No.	Quantity /Product Sp	Spill S	lite	Reason for being Reportable					
1	50L/ Activa sludge	Waste Treati	Camp — Water nent (WWTP)	Reportable (on-land). A fitting at the alum injection point corroded and cracked spilling waste activated sludge into a on-site building and onto the ground. Some of the material sprayed in the UV/blower building and some spilled under the building onto the ground. The spilled material was contained in a soil containment area and cannot flow to the nearby Mattagami River. The union was cut and capped and a new injection point was drilled into the pipe.					
	KAP Project Classification Minor: $\leq 10L$			MOE Classification (see Reportable and Non-reportable Spills definition below)					
Moderate: Between 10L and 100L		.00L	Non-reportable: < 100L						
Major: ≥100L			Reportable to MOE						
To Water: Any amount is reportable to		rtable to	Class C - Less Serious						
the MOE		200	Class B – Serious						
(See Figure 7: KAP Spills Response Flowchart)			JIISE	Class A – Very Serious					
Sediment Pond Exceedance of Effluent Objective									
	No. of	Location		Mitigation Measures used					
Exc	eedance								
days	recorded								
	n/a								

Monthly Summary – July 2014

Spills Response

When **any spill** occurs on site, KAPs spill response process is to be followed (Figure 7). This includes notification of the Supervisor and KAPs Environmental Department, and an assessment of the severity of the spill. Regardless of the quantity, clean-up measures are implemented for **every spill** using spill kits that are available throughout the site (materials used for clean-up and any contaminated soil are removed from the site). A spill report is then prepared for **each spill that occurs** which outlines the location, type, severity and quantity of the spill, in addition to details on how the spill occurred, how it was cleaned up and measures implemented on how the spill could be avoided for the future. This report is sent out to several OPG and Hatch representatives as well as all EWG members.

Reportable and Non-reportable Spills:

Section 92 of the *Environmental Protection Act* (EPA) requires that **a spill** be reported forthwith to the Ministry of the Environment. The definition of a spill in the EPA (subsection 91.1) is: a discharge,

- (a) into the natural environment,
- (b) from or out of a structure, vehicle or other container, and
- (c) that is abnormal in quality (e.g. the product spilled) or quantity (e.g. the amount spilled) in light of all the circumstances of the discharge.

Spills that are exempt from reporting to the Ministry of the Environment (ie. non-reportable) are discharges that don't fall within the 'spill' definition or, are exempted under EPA Regulation 675/98, *Classification and Exemptions of Spills and Reporting of Discharges*. This includes (not limited to) Class VI – Motor Vehicle exemptions, which exempts reporting of spills that are less than 100 L of fluid from a motor vehicle.

Subsection 30 .2 of the *Ontario Water Resources Act*, requires that the discharge of any material of any kind into water that is not in the normal course of events (e.g. regardless of quantity or quality) be reported to the Ministry of the Environment.

Lower Mattagami River Project Spills 30 500 Reportable (in Water) Reportable (on Land) 450 Non-Reportable 25 Total Spills 400 350 20 Spils for the Month 300 15 250 200 10 150 100 5 50 0 Sep 2013 Jul 2012 Jul 2013 Sep 2010 Jul 2011 Jan 2012 Jan 2013 Nov 2012 May 2013 Jan 2014 May 2010 Nov 2010 Jan 2011 May 2011 Sep 2011 Mar 2012 May 2012 Sep 2012 Mar 2013 Nov 2013 May 2014 Jul 2014 Jul 2010 Mar 2011 Nov 2011 Mar 2014 Month / Year

Figure 6: Lower Mattagami River Project spills




Figure 7: KAP Spills Response Flowchart


No.	PERMIT AND/OR APPROVAL REVIEW	Reviewed by EWG	Submitted to KAP
-	0	0	0


Monthly Permit and Approval Review Table


Provincial Environmental Assessment Term and Condition (EA T&C) Reports Review and Environmental Audits Table


No.	Report or Audit	Applicable EA T&C	Reviewed or Under Review	Submitted to KAP	Submitted to MECC
			by EWG	-	
14	KAP Kipling Site Rehabilitation Plan.	3a and 5	9	e	-
13	KAP Harmon Site Rehabilitation Plan.	3a and 5	۲	۲	-
12	Cost Benefit Analysis of Mitigating and Reducing Spill in Adam Creek	4c	۲	n/a	-
11	Mercury in Fish Flesh Summary Report	4b and 7a	۲	n/a	-
10	Fish Habitat Assessment Report	4b	۹	n/a	-
9	Terrestrial Habitat Restoration Downstream of Kipling GS	5b	۹	n/a	-
8	Draft Environmental Effects Monitoring Plan	3a, 4b, 5b, 6, 7 and 14	۹	n/a	-
7	KAP Little Long Site Rehabilitation Plan.	3a and 5	۹	۲	-
6	Operation Overview Report	4a	۹	n/a	۲
5	Waste Management Plan	19	۹	۲	۲
4	Noise Control Plan	18	٩	۲	۲
3	The Interim Measures Agreement as it relates to EA Term and Condition 14c (Permit Review and Compliance Monitoring Protocol)	14c	۲	٠	٠
2	2013 Environmental Audit	14	۲	۲	۲
1	2012 Environmental Audit	14	۲	۲	۲














Issues and Concerns

• The members of the EWG still had concerns with the potential for bear mortalities before other mitigation measures were exhausted.

Action required: KAP to follow process provided by MCFN that included the readjustment of traps, and the introduction of using rubber bullets before shooting of bears was to occur.

• The MCFN members of the EWG had concerns with pipe insulation leftover at the Kipling Sediment Pond area.

Action required: KAP to ensure all pipes and pipe insulation are removed from the Kipling Sediment Pond area.